School Facilities Survey ED050, Rev August 2011 Statutory Ref: C.G.S. 10-220

46

Overall Indoor Air Quality

4 (Scale: 4 = excellent, 3 = good, 2 = fair, 1 = poor. See instructions for detailed explanation)

State Of Connecticut Department Of Education Bureau of School Facilities 165 Capitol Avenue Hartford, CT 06106-1630

Town: 080-Meriden School: 052-Lincoln Middle School Page 1 of 2 Check box if this facility is no longer used for school purposes Year facility closed Section 1: Using the instruction booklet accompanying this survey, for questions 10 through 40 review the description of each item and respond accordingly. 0 Year of original construction: 2005 Number of portable classrooms: In use since (year): 2 Total square footage: 132300 6a 0 3 Total site acreage: 11.97 7 Handicap accessibility (check one): **AllAreas** 8 Major code update since 1988: Yes 4 Year of last major renovation: 0 5 Number of general classrooms (perm): 30 9 **Building Capacity:** 750 Section 2: Using the instruction booklet accompanying this answer sheet, review the description of the choices that are provided for each item and select the one that best describes your school. Select one answer only for each item and report the number associated with that choice in the space provided. . Rating **Building Features:** Rating (Scale: 4 = excellent, 3 = good, 2 = fair, 1 = poor, 0 = missing. See instructions for detailed explanation) **Dedicated Specialty Areas** Technology in the classroom Art Room(s): 10 18 11 Music Room(s): 19 Science Lab(s) Library Media Center 12 All Purpose Room (Gym/Aud/Caf.) 20 13 Gymnasium: 21 Language Lab(s) Technical/Career Education 22 14 Auditorium: Office/Administrative Space 15 Cafeteria: 23 16 Outdoor Play Area(s): 24 Guidance/Student Services 17 Outdoor Athletic Facilities Systems Internal Communications 29 Interior Lighting 25 30 **Exterior Lighting** 26 Technology Infrastructure Roadways and Walks 27 Air Conditioning 31 Heating 32 Plumbing/Lavatories 28 Appearance/Upkeep Entrance/Hallways 33 **Building Facade** 37 38 Lighting/Fixtures 34 Grounds/Landscaping 35 39 Cafeteria Classrooms 36 Lavatories/Fountains 40 Code Compliance **Building Conditions** Indoor Air Quality (IAQ) Has this facility been constructed, extended, renovated or replaced on or after January 1, 2003? Yes 41 If yes, please continue. If no, go to Question 45. Has the district provided for a uniform inspection and evaluation program of the indoor air quality within this building, 42 such as Environmental Protection Agency's Indoor Air Quality Tools for Schools? Yes (Not required until Jan. 1, 2008). If yes, please continue. If no, go to Question 45. Tools for Schools 43 Please indicate the program chosen: Other Name of other program: _ If Tools for Schools, please enter date (as mm/dd/yyyy) trained by State Dept. of Public Health 2/7/2008 or indicate 44 that training is pending. If "Other" was selected above, please indicate whether or not the selected program provides for reviews, inspections, and evaluations of each of the following: Degree of pesticide usage Radon levels in water and air **HVAC Systems** Ventilation systems Microbiological particles Chemical compounds Hazardous substances Plumbing Pest infestation Staff maintenance training Structural elements Use of space Overall cleanliness Moisture incursion With respect to this facility and the Overall Indoor Air Quality rating, for each of the following issues, indicate either 45 1) was a problem but has been corrected; 2) identified as a problem but issue not addressed yet; 3) problem identified and scheduled for repair; or 4) not a problem. Obstructions of air vents 4 Radon remediation needed Leaks (other than roof), spills, moisture Filters need upgrading or replacing Asbestos remediation needed Plumbing problems General cleaning improvement Roof problems HVAC units/ventilators need cleaning Arts/sciences room(s) need ventilating Basement or crawlspace needs upgrading Carpet cleaning or removal needed Outdoor air intakes need improving Pests or pesticide use remediation Removal of water-damaged materials needed Classroom animal dander exposure _4_ Bus exhaust